

Yellow melt/ppt (?) that has fused the bottom of the insert to the oxidation column

Broken bottom of quartz insert

Tin that has left eroded insert slit and fused to side of oxidation column

